MATERIAL SAFETY DATA SHEET
May be used to compty with
OSHA's Hazard Communication
Standard, 29 CFR 1910.1200,
Standard must be consulted
for specific requirements.

(Reproduce Locally)

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration (Non Mandatory Form) Form Approved OMB No. 1218-0072 H.M.I.S. RATING
HEALTH: 1
FLAMMABILITY: 2
REACTIVITY: 0
PERSONAL PROTECTIVE EQUIP.:

OSHA 174, Sept. 1985

ASPHALT COMPOUND IDENTITY (as used on label and list) NOTE: Blank spaces are not permitted, if any item is not applicable, or no information is available, the space must be marked to indicate that. MONSEY UNFIBERED ROOF/FOUNDATION CTG. SECTION I **Emergency Telephone Number** Manufacturer's Name MONSEY BAKOR 610-933-8888 ADDRESS (Number, Street, City, State and Zip Code) Telephone Number for Information 610-933-8888 P.O. BOX 368 COLD STREAM ROAD **Date Prepared** Supersedes Sheet # 1 8/5/97 4/25/94 KIMBERTON, PA 19442 Signature of Preparer (optional) SECTION II HAZARDOUS INGREDIENTS/IDENTITY INFORMATION Other Limits Hazardous Components (Specify Chemical Identity; Common Name(s)) OSHA PEL ACGIH TLV Recommended %(optional) CAS# 100 PPM Petroleum Distillate 8052-41-3 5mg/M3 <u>Asphait</u> 8052-42-4 THERE ARE NO SARA 313 INGREDIENTS IN THIS MATERIAL IN EXCESS OF DEMINIMUS AMOUNTS. SECTION III PHYSICAL/CHEMICAL CHARACTERISTICS 7.7 310 - 400°F Soiling Pt. Weight per gallon Vapor Pressure(mm Hg) 2@ 68°F **Melting Point** N/A Liquid Vapor Density(Air=1) Heavier Evaporation Rate (Butyl Acetates1) Slower Solubility in Water None Appearance and Odor Black fluid, Odor characteristic of Petroleum Solvent SECTION IV FIRE AND EXPLOSION HAZARD DATA FLASH POINT (Method Used): SETA 105°F Flammable Limits 0.9% UEL 6.0% EXTINGUISHING MEDIA: Foam, CO2, Dry Chemical, Water Fog, Spray SPECIAL FIRE FIGHTING PROCEDURES: N/A UNUSUAL FIRE AND EXPLOSION HAZARDS: DO NOT MIX OR STORE WITH STRONG OXIDANTS LIKE LIQUID CHLORINE OR OXYGEN. KEEP CONTAINERS TIGHTLY CLOSED. CLOSED CONTAINERS MAY EXPLODE WHEN EXPOSED TO EXTREME HEAT APPLICATION TO HOT SURFACES REQUIRES SPECIAL PRECAUTIONS. DURING EMERGENCY CONDITIONS, OVEREXPOSURE TO DECOMPOSITION PRODUCTS MAY CAUSE A HEALTH HAZARD. SYMPTOMS MAY NOT BE IMMEDIATELY APPARENT. OBTAIN MEDICAL ATTENTION.

SECTION V RE	ACTIVITY D	ATA							
STABILITY	Unstable		Conditions to	avoid					
	Stable	X			- 	<u> </u>			
INCOMPABILITY (N	Saturiale to Av	nielle S	trong Ovidante						
· · · · · · · · · · · · · · · · · · ·									
HAZARDOUS DEC	OMPOSITION (OR BYP	RODUCTS: Fu	mes, Smok	e, and CO ₂ ; C	Carbon Monoxid	e if combu	stion is incomplete.	
HAZARDOUS POLYMERIZATION	May Occur		Conditions to A	void					
	Will not Occur	X							
SECTION VI H	EALTH HAZ	ARD I	DATA						
ROUTE(S) OF ENT				Eyes?	YES	Skin?	YES	Ingestion?	YES
HEALTH HAZARD	S (Acute and C	hronic)	and Signs of Sy	mptoms of	Exposure:	Over exposure	to vapors	causes eye irritation,	blurred
vision, dizziness, he	adaches, even u	insconso	iousness. Prolon	ged or repe	ated skin con	itact can cause	moderate	rritation, defatting, de	rmatitis.
Swallowing can caus which can be fatal.	se gastrointestin	al irritatio	on, nausea, vomiti	ng, and dia	rrhea. Aspira	tion of material	into lungs	can cause chemical p	neumonitis
Willest Cust De Tatal.							· · · · ·		
								 	
EMERGENCY AND irregular, start resus				from vapor	immediately.	If overcome, ca	ill a physic	ian. If breathing stop	ped or
IF IN EYES: Flush	with large amou	ints of w	ater, lifting upper	and lower li	ds occasiona	lly. Get medica	attention.		
IF ON SKIN: Rem	ove contaminate	d clothes	and wash with w	rateriess ha	ndcleaner or	soap and water		 -	
IF INGESTED: DE	not induce von	niting.							
			 					·	
SECTION VII	PRECAUTIO	NS F	OR SAFE HAI	NDLING	AND USE				
27502 70 25 74	/				.50. 0				
								ep people away. Rec es. Open all window	
Keep products out of									
WASTE DISPOSA	L METHOD: A	ssure co	nformity with app	licable disp	osal regulatio	ns.		·—·	
	 _							 	
PRECAUTIONS TO sparks, flame, or st					p containers	closed when no	tin use. [o not handle or store	near heat,
							_		
								ontaminated clothing and water after contact	
									
SECTION VIII	CONTROL	MEAS	URES						
				arbon vapo	x canister/ su	ipplied air resp.	protection	in confined/encl. spa	ces if needed
			CHAUST:		ocity 60fpm				
VENTILATION	S	PECIAL:		Use only	with adequat	e ventilation			
	M	ECHANI	CAL (General):	N/A					
	0	THER:		N/A	 				
PROTECTIVE GL			esistant gloves if				kin contac		
OTHER PROTECTION	N: Use splash	goggles	or face shield wh	en eye con	tact may occu	uf.	ina in		
WORK HYGENIC	PRACTICES:		ractice good world		esistant apro	ni or other cloth	nid to svok	d repeated or prolong	ed skin contact.
	<u></u>				PAGE 2		 -		